



# Certificate of Registration

*This is to certify that compliance of Quality Management System of*

## **PT. HELORI GRAHASARANA**


Head Office :  
Puri Sentra Niaga Blok A-16,  
Jl. Raya Kalimalang,  
Jakarta 13620

Work Shop :  
Kp. Cikuda,  
Desa Bojong Nangka RT 26/12,  
Kec. Gunung Putri, Kab. Bogor

*has been assessed and found to conform the requirement of*

## **ISO 9001:2015**

*For the scope of activities*




**Fabrication of Delta Pole (Polygonal Pole) Steel for Highways,  
Stadium, Harbour, Airfield, Fabrication of Guardrail Steel,  
Spare Part for Machine Tool and Electrical and  
Telecommunication Accessories**

Certificate No. : QMSI/158


Certificate Date : 20.06.2017

ANAS-BNR Certificate No. : 10918

Certificate Valid Upto : 18.06.2018

Surveillance Audit : 2nd Year 08.06.2016 

For and on behalf of Bureau of International Quality Standard

3rd Year 08.06.2017 



The certificate is valid only if the annual surveillance marks is present

Head of Certification



Quality Seal



***Bureau of International Quality Standard Pte. Ltd***

**Blk 464, Choa Chu Kang, Avenue -4, #02-29, Singapore-680 464, [www.biqs.org](http://www.biqs.org)**

**Accredited by : ANAS - BNR (American National Accreditation Services - Bureau of Notified Registrar )**

**2711 Centerville Road, Suite 400, Wilmington, Delaware, 19808 (U.S.A.)**

The Registration does not assure the quality of yields under the firm's production